

# Impedance Matching Transformers

## #90-449x



Impedance Matching Transformer

### #90-4495 - Step Up

- Fq 500kHz to 5MHZ
- Power 200W Max.
- Input = 50 Ohm
- Output =90, 140, 210, 280 Ohm
- BNC Connectors

### #90-4497 - Step-Up

- Fq 20kHz to 1MHZ
- Power 200W Max.
- Input = 50 Ohms
- Output = 90, 140, 210, 280 Ohm
- BNC Connectors

### #90-4496 - Step Down

- Fq 20KHz to 1MHz
- Power 200W Max.
- Input = 50 Ohm
- Output =9, 16, 25, 38 Ohm
- BNC Connectors

### #90-4498 - Step-Down

- Fq 500kHz to 5MHz
- Power 200W Max.
- Input = 50 Ohms
- Output = 9, 16, 25, 38 Ohm
- BNC Connectors

**\*\*Call APC for Additional Information\*\***

